

OLLORTÉELS STEELTO Care & Maintenance.

Powder coating; can be cleaned with a soft damp cloth (non-abrasive). Mild detergent in warm water can be used to remove dust and other stubborn deposits (DO NOT use solvents). Thoroughly clean the surface of all detergents with fresh water afterwards. (DO NOT let water sit for extended periods of time). Glass; Only use products specifically designed for cleaning glass. Prepare the surface with a damp cloth to remove all dust and dirt. (DO NOT use abrasive or sharp edged tools).